




Fiberglass Tubs & Showers

Those hairline cracks seem so harmless, but can end up costing you a bundle or worse !



Your home inspector pointed out hairline cracks in the fiberglass tub or shower and said something about improper support from underneath. You look at the cracks and decide they are too small to worry about - - two years later the tub or shower needs to be replaced ... what happened?

Improper support under the tub floor or shower pan allows for movement or flexing when weight is applied causing what appears to be hairline cracks. These minor cracks will open wider with the weight of someone standing in the tub and continue to grow over time.

Don't be fooled by these seemingly small cracks in the tub floors or shower pans. Repairs maybe simple if caught early enough.



REPAIRS